

1	Machine cover
2	Machine base
3	Transformer
4	Temperature controller 95°C
5	Rectifier bridge
6	Support foot
7	axle 8*370
8	wheel
9	Panel
10	Handle
11	current meter 85c1
12	fuse cover
13	charging clamp 200A
14	fuse 100A
15	cable binding post
16	Power cable
17	cable connect place
18	333 binding post
19	30A switch(white/ 3 pins)
20	30A switch(4 pins)
21	splitter
22	M5 nut
23	M5 washer
24	M5 spring washer
25	M5 screw
26	Holder
27	back cover
28	M5 screw

